



Architects

John G. Waite Associates PLLC

HISTORIC PRESERVATION · RESTORATION · ADAPTIVE USE

John G. Waite Associates, PLLC Architects

384 Broadway | Albany, NY 12207 | 518.449.5440
64 Fulton Street | New York, NY 10038 | 212.619.4881
www.jgwaarchitects.com

The recent completion of a comprehensive Historic Structure Report (HSR) for the **Statue of Liberty** marked the third in a line of studies completed by **John G. Waite Associates, Architects** for the iconic structure.

JGWA began working with the National Park Service (NPS) on a Risk Assessment Report following the attacks of September 11th. The firm then prepared a Historic Structure Report for Fort Wood, the star-shaped fort in New York Harbor on which the Statue rests. The Statue of Liberty HSR, the third report, was a culmination of the long-term relationship between **JGWA** and the NPS at Liberty Island. The HSR thoroughly assesses the history, evolution, and existing conditions of the Statue and pedestal to guide its future preservation.

John G. Waite Associates, Architects is a nationally recognized leader in the preservation, restoration, and adaptive use of historic properties. For more information please visit www.jgwaarchitects.com

